

Customer Changes in *HBLT* application from version 2.30 to version 2.31

Author: Charles E. Southward

Date: January 25, 2005

This version makes the following changes:

1. Corrected a programming error that sent the "Invalid number of ports selected" message when the Smart Manifold mode changed from single to sequential or parallel in combination with multiple ports selected.
2. Corrected a programming error that reset the Smart Manifold if the last test run on the HBLT was a single port mode test and number of ports selected was greater than one.