

# Changes For HBLT Version 2.45

Author: Charles E. Southward

Date: March 5, 2007

Revised: March 5, 2007

This version makes the following changes:

1. Corrected a software error that skipped the next selected port after a burst or leak event when running a script with a Smart Manifold in sequential mode.