

Changes For HBLT Version 1.91

Author: Charles E. Southward

Date: August 8, 2001

Revised: August 8, 2001

This version makes the following changes:

1. Removed 1800 HBLT model type.
2. Added DELIVER VOLUME, REMOVE VOLUME, VOLUME RATE, and VOLUME PRESS LIMIT commands and state machine code to implement these functions.
3. Added volume correction table calibration to purge screen. This allows the customer to change the default volume correction table for more accurate results with the Pressure Manager volume features.
4. Corrected error handling for !MS, !OT, !OP, !EN, !HT, and !ES alarms. These alarms now work correctly in Pressure Manager script and test modes.